Version 3

SINGAPORE 1.8

> 870 773 183 408 783183052

eagle.kangar@aet-tankers.com

Oil Tanker

Double Hull

+1001 A1 Double Hull Oil Tanker, ESP, CSR, LMC\*IV, UMS

N/A

No.

new build

Jun 21, 2015

Jun 21, 2015

(NA)

N/A

Summer Dwt

Collapsed Mast

ED\_002238\_00001575-00001

49.30 m

121.25 m

69.15 m

42.76 m

111.91 m

330 mm

46.880 m

41.26 m

34.722 m

60379

61666.83

Normal Ballast

Full Mast

32114

Lightship

67.84 m

36.24 m

104.08 m

Jun 21, 2015

243.8 m

42.032 m

122.55 m

85.63 m

69.15 m

126.51 m

95.21 MT

0.000 m

0.000 m 0.000 m

47691

57581.32

57 m

237 m

21.3 m

0 m

456375911

Lloyds Register

Not Applicable

Not Applicable

Port of Registry: 9V8472 Call sign:

INTERTANKO'S STANDARD TANKER CHARTERING QUESTIONNAIRE 88 (Q88)

1.

1.9

VESSEL DESCRIPTION

1.10 Vessel's satcom phone number:

Vessel's fax number: Vessel's telex number:

Vessel's email address:

1.15 If Classification society changed, name of previous society:

1.18 Does the vessel have ice class? If yes, state what level:

1.23 If ship has Condition Assessment Program (CAP), what is the latest overall rating:

1.24 Does the vessel have a statement of compliance issued under the provisions of the

Condition Assessment Scheme (CAS): If yes, what is the expiry date?

1.29 Keel to Masthead (KTM) / KTM in collapsed condition (if applicable):

1.30 Bow to Center Manifold (BCM) / Stern to Center Manifold (SCM):

1.16 If Classification society changed, date of change

1.21 Date of last special survey / next survey due:

1.26 Length Between Perpendiculars (LBP):

Forward to mid-point manifold:

At loaded summer deadweight:

Aft to mid-point manifold:

Parallel body length:

Lightship:

1.35 Net Tonnage:

Tonnages

Normal ballast:

Distance bridge front to center of manifold:

1.33 FWA at summer draft / TPC immersion at summer draft:

1.34 What is the max height of mast above waterline (air draft)

1.36 Gross Tonnage / Reduced Gross Tonnage (if applicable):

1.37 Suez Canal Tonnage - Gross (SCGT) / Net (SCNT):

1.11 Type of vessel:

1.14 Class notation:

1.13 Classification society:

1.17 IMO type, if applicable:

1.20 Date next dry dock due

1.25 Length Over All (LOA):

1.27 Extreme breadth (Beam):

1.32 Parallel body distances:

1.28 Moulded depth:

1.22 Date of last annual survey:

1.19 Date / place of last dry-dock:

1.12 Type of hull:

Classification

**Dimensions** 

1.31

1.38	Panama Canal Net Tonnage (PCNT):				
Load	lline Information			***************************************	
1.39	Loadline Fr	eeboard	Draft	Deadweight	Displacement
	Summer:	6.766 m	14.578 m	107481 MT	125524 MT
	Winter:	7.069 m	14.275 m	104598 MT	122641 MT
	Tropical:	6.463 m	14.881 m	110367 MT	128410 MT
	Lightship:	18.924 m	2.42 m		18043 MT
	Normal Ballast Condition:	13.304 m	8.04 m	46.396 MT	64439 <b>M</b> T
1.40	Does vessel have multiple SDWT?				Yes
1.41	If yes, what is the maximum assigned deadweigh	nt?			107481 MT
Own	ership and Operation				
1.42				AET INC LTD AET INC LTD. Cumberland House 9th Floor, 1 Victoria Street, Hamilton HM 11, Bermuda Tel: +1-832-615-2000 Fax: +1-713-622-2256 Email: 'aet-ops@aet-tankers.com' Company IMO#: 1584384	
1.43	Technical operator - Full style:			AET Shipmanagement (Singapore) Pte Ltd AET Shipmanagement (Singapore) Pte. Ltd, 1 Harbour Front Avenue, # 11-02 Keppel Bay Tower Singapore 098632 Tel: +65-61002288 Fax: +65-62760735 Telex: RS 20155 AET Email: Team-Atl@aet-tankers.com Web: aet-tankers.com Company IMO#: 5034289	
1.44	Commercial operator - Full style:			AET INC .LTD 1900 WEST LOOP SOUTH, SUITE 920,HOUSTON TEXAS 77027 U.S.A. Tel: +1 832 615 2013 Fax: +44 20 7538 8383 Email: aet-ops@aet-tankers.com	
1.45	15 Disponent owner - Full style:			N/A	
2.	CERTIFICATION		Issued	Last Annual or Intermediate	Expires
2.1	Safety Equipment Certificate:		Jun 22, 2010	Jun 24, 2011	Jun 21, 2015
2.2	Safety Radio Certificate:		Jun 22, 2010	Jun 24, 2011	Jun 21, 2015
2.3	Safety Construction Certificate:		Jun 22, 2010	Jun 24, 2011	Jun 21, 2015
2.4	Loadline Certificate:		Jun 22, 2010	Jun 24, 2011	Jun 21, 2015
2.5	International Oil Pollution Prevention Certificate (	IOPPC):	Jan 05, 2011	Jun 24, 2011	Jun 21, 2015
2.6	Safety Management Certificate (SMC):		Dec 10, 2010	Nat April II	Dec 09, 2015
2.7	Document of Compliance (DOC):		Jun 23, 2011	Not Applicable	Jul 01, 2013
2.8	USCG (specify: COC, LOC or COI): COC		Feb 08, 2011	Not Applicable	Feb 08, 2013
2.9 2.10	Civil Liability Convention Certificate (CLC): Civil Liability for Bunker Oil Pollution Damage Co	nvention	Feb 03, 2012 Feb 03, 2012		Feb 20, 2013 Feb 20, 2013
	Certificate (CLBC):	~			
	U.S. Certificate of Financial Responsibility (COFF	≺):	Jun 28, 2010		Apr 20, 2013
	Certificate of Fitness (Chemicals):				
	Certificate of Fitness (Gas):		l 05 0044	h 04 0045	l 04 0045
	Certificate of Class:		Jan 05, 2011	Jun 21, 2015	Jun 21, 2015
	International Ship Security Certificate (ISSC):	((0000)	Dec 10, 2010		Dec 09, 2015
	International Sewage Pollution Prevention Certification		Jun 24, 2011		Jun 21, 2015
	International Air Pollution Prevention Certificate (	IAPP):	Jun 24, 2011	Jun 24, 2011	Jun 21, 2015
	umentation  Does vessel have all updated publications as listed in the Vessel Inspection Questionnaire, Chapter 2- Question 2.24, as applicable:			Yes	
				ED	0_002238_00001575-00002

2.19	Owner warrant that vessel is member of ITOPF and will remain so for the entire duration of this voyage/contract:	Yes
3.	CREW MANAGEMENT	
3.1	Nationality of Master:	Indian
3.2	Nationality of Officers:	Malaysian, Chinese, Indian, Bangladeshi, Filipino, Ghanaian, Ukrainian
3.3	Nationality of Crew:	Filipino, Malaysian, Singaporean
3.4	If Officers/Crew employed by a Manning Agency - Full style:	Officers: Vessel Operator Not Applicable Crew:
3.5	What is the common working language onboard:	English
3.6	Do officers speak and understand English:	Yes
3.7	In case of Flag Of Convenience, is the ITF Special Agreement on board:	N/A
4.	HELICOPTERS	
4.1	Can the ship comply with the ICS Helicopter Guidelines:	Yes
4.2	If Yes, state whether winching or landing area provided:	Landing
5.	FOR USA CALLS	
5.1	Has the vessel Operator submitted a Vessel Spill Response Plan to the US Coast Guard which has been approved by official USCG letter:	Yes
5.2	Qualified individual (QI) - Full style:	Galaghar Marine Systems 200Century Parkway, Suite D Mt.Laurel, NJ 08054 Tel: +1 703 683 4700 Fax: +1 856 642 3945 Email: info@chgms.com
5.3	Oil Spill Response Organization (OSRO) -Full style:	Marine Spill Responce Corporation 220 Spring Street, Suite 500, Herdon, VA 20170 Tel: +17324170175 Fax: +17324170097 Email: AMPD@MRSC.ORG
5.4	Has technical operator signed the SCIA / C-TPAT agreement with US customs concerning drug smuggling:	Yes
6.	CARGO AND BALLAST HANDLING	
Doul	ole Hull Vessels	
6.1	Is vessel fitted with centerline bulkhead in all cargo tanks:	Yes
	If Yes, is bulkhead solid or perforated:	Solid
Carg	o Tank Capacities	
6.3	Capacity (98%) of each natural segregation with double valve (specify tanks):	Seg#1: 40623.4 m3 (1W , 4 W, SL-S) Seg#2: 41623 m3 (2W, 5W) Seg#3: 42700.5 m3 (3W, 6W SL-P)
6.4	Total cubic capacity (98%, excluding slop tanks):	121064.600 m3
6.5	Slop tank(s) capacity (98%):	3902.400 m3
6.6	Residual/Retention oil tank(s) capacity (98%), if applicable:	m3
6.7	Does vessel have Segregated Ballast Tanks (SBT) or Clean Ballast Tanks (CBT):	SBT
SBT	Vessels	
6.8	What is total capacity of SBT?	42017 m3
6.9	What percentage of SDWT can vessel maintain with SBT only:	40 %
6.10	Does vessel meet the requirements of MARPOL Annex I Reg 18.2: (previously Reg 13.2)	Yes
Carg	o Handling	
6.11	How many grades/products can vessel load/discharge with double valve segregation:	3
6.12	Maximum loading rate for homogenous cargo per manifold connection:	3949 m3/hr
6.13	Maximum loading rate for homogenous cargo loaded simultaneously through all manifolds:	11847 m3/hr
		ED_002238_00001575-00003

6.14	Are there any cargo tank filling restrictions. If yes, please speci	ify:		No	
Pum	ping Systems				
6.15	Pumps:	No.	Туре	Capacity	
	Cargo:	3	Centrifugal	3000 M3/HR	
	Stripping:	1	Reciprocating	200 m3/hr	
	Eductors:	1	Other	450 m3/hr	
	Ballast:	2	Centrifugal	1800 m3/hr	
6.16	How many cargo pumps can be run simultaneously at full capa	 acity:	3		
Carg	o Control Room				
	Is ship fitted with a Cargo Control Room (CCR):			Yes	
	Can tank innage / ullage be read from the CCR:		Yes		
	ging and Sampling				
	Can ship operate under closed conditions in accordance with I	SGOTT <sup>.</sup>		Yes	
	What type of fixed closed tank gauging system is fitted:		Radar		
	Are overfill (high-high) alarms fitted? If Yes, indicate whether to	all tanks or nartial	ALL COT		
	or Emission Control	o an tariks or partial.	ALLOOT		
•	ls a vapor return system (VRS) fitted:			Yes	
	Number/size of VRS manifolds (per side):		2	1 400 mm	
				400 111111	
Vent				ananan Lina	
	State what type of venting system is fitted:		C	ommon Line	
	o Manifolds				
6.25	Does vessel comply with the latest edition of the OCIMF 'Reco Tanker Manifolds and Associated Equipment':	mmendations for Oil		Yes	
6.26	What is the number of cargo connections per side:		3		
	What is the size of cargo connections:			400 mm	
	What is the material of the manifold:		STEEL		
	fold Arrangement				
	Distance between cargo manifold centers:			2500 mm	
	Distance ships rail to manifold:			4600 mm	
	Distance manifold to ships side:	4600 mm			
	Top of rail to center of manifold:		700 mm		
	Distance main deck to center of manifold:		2075 mm		
		T condition:	15.379 m 8.841 m		
	Manifold height above the waterline in normal ballast / at SDW	1 CONGILION.			
b.35	Number / size reducers:	3 x 400/200mm (16/8") 3 x 400/250mm (16/10")			
		3 x 400/300mm (16/12")			
Sterr	n Manifold				
6.36	ls vessel fitted with a stern manifold:		No		
6.37	If stern manifold fitted, state size:			mm	
Carg	o Heating				
6.38	Type of cargo heating system?		STEAM		
6.39	If fitted, are all tanks coiled?		Yes		
6.40	If fitted, what is the material of the heating coils:	Stainless Steel			
6.41	Maximum temperature cargo can be loaded/maintained:		66.0 °C / 150.8 °F	66 °C / 150.8 °F	
Tank	Coating				
6.42	Are cargo, ballast and slop tanks coated?	Coated	Туре	To What Extent	
	Cargo tanks:	Yes	PURE EPOXY	CROWN 2.0M & TANK BOTTOM	
	Ballast tanks:	Yes	PURE EPOXY	Whole Tank	
	Slop tanks:	Yes	PURE EPOXY	Whole Tank	
6.43	If fitted, what type of anodes are used:		Zinc	······································	
			i		
7.	INERT GAS AND CRUDE OIL WASHING				
:			EI	D_002238_00001575-00004	

7.1	Is an Inert Gas System (IGS) fitted:			Yes		
7.2	Is IGS supplied by flue gas, inert gas (IG) ger	nerator and/or nitroge	•n:	Flue Gas		
7.3	Is a Crude Oil Washing (COW) installation fitt	ed:			Yes	
				<u></u>		
8.	MOORING					
8.1	Mooring wires (on drums) No.	Diameter	Material	Length	Breaking Strength	
	Forecastle: 4	36 mm	ISWR	250 m	85 MT	
	Main deck fwd: 4	36 mm	ISWR	250 m	85 MT	
	Main deck aft: 2	36 mm	ISWR	250 m	85 MT	
	Poop deck: 6	36 mm	ISWR	250 m	85 MT	
8.2	Wire tails No.	Diameter	Material	Length	Breaking Strength	
	Forecastle: 4	80 mm	NYLON	11 m	120 MT	
	Main deck fwd: 4	80 mm	NYLON	11 m	120 MT	
	Main deck aft: 2	80 mm	NYLON	11 m	120 MT	
	Poop deck: 6	80 mm	NYLON	11 m	120 MT	
8.3	Mooring ropes (on drums) No.	Diameter	Material	Length	Breaking Strength	
0.0	Forecastle:	mm	Material	m	MT	
	Main deck fwd:	mm		m	MT	
	Main deck iwd.				MT	
	Poop deck:	mm		m	MT	
8.4	ļ	mm Diameter	Material	l angth		
0.4	Other mooring lines No.	Diameter		Length	Breaking Strength	
	Forecastle: 2	80 mm	BRID	220 m	85 MT	
	Main deck fwd:	mm		m	MT	
	Main deck aft: 1	80 mm	BRID	220 m	85 MT	
	Poop deck: 2	80 mm	BRID	220 m	85 MT	
8.5	Mooring winches No.			# Drums	Brake Capacity	
	Forecastle: 4			Double Drums	44 MT	
	Main deck fwd: 4			Double Drums	44 MT	
	Main deck aft: 2			Double Drums	44 MT	
	Poop deck: 6			Double Drums	44 MT	
8.6	Mooring bitts			No.	SWL	
	Forecastle:			4	92 MT	
	Main deck fwd:			6	92 MT	
	Main deck aft:			4	92 MT	
	Poop deck:			4	92 MT	
8.7	Closed chocks and/or fairleads of enclosed type			No.	SWL	
	Forecastle:			8	85 MT	
	Main deck fwd:			14	85 MT	
			Main deck aft:	8	85 MT	
			Poop deck:	13	85 MT	
Eme	rgency Towing System					
8.8	Type / SWL of Emergency Towing system forward:			TONGUE	250 MT	
8.9	Type / SWL of Emergency Towing system aft:			KETA-40A .	200 MT	
Anc	nors					
8.10	Number of shackles on port cable:			13		
8.11	Number of shackles on starboard cable:			13		
Esco	ort Tug			······································		
8.12	What is SWL and size of closed chock and/or	fairleads of enclose	d type on stern:	200 MT	360	
8.13	What is SWL of bollard on poopdeck suitable	for escort tug:			200 MT	
	/Stern Thruster	<del>.</del>		·······		
8.14	What is brake horse power of bow thruster (if	fitted):		bhp	0 Kw	
				<u> </u>		
				EC	0_002238_00001575-00005	

8.22   What is the maximum size chain diameter the bow stopper(s) can handle   76 8 22   Distance between the bow fairlead and chain stopper/bracket   3000   3000   328   36 bow chock and/or fairlead and chain stopper/bracket   3000	8.15	What is brake horse power of stern thruster (if fitted):	bhp	0 Kw
Equipment Employed in the Mooring of Vessels at Single Point, Moorings (SPM)	Sing	le Point Mooring (SPM) Equipment	······································	
1	8.16			Yes
3.29   State type of chain stopper(s) (fitad   2.28   320   320   420   320   320   420   320   320   420   320   320   420   320   320   420   320	8.17	Is vessel fitted with chain stopper(s):		Yes
2.20   Safe Working Load (SWL) of chain stopper(s)	8.18	How many chain stopper(s) are fitted:		2
8.21   What is the maximum size chain diameter the bow stopper(s) can handle. 8.22   Distance between the bow fairfead and chain stopper/brocket. 8.23   Is bow chander fairlead of a facility of the properties of the stopper of the	8.19	State type of chain stopper(s) fitted:	TONGUE TYPE	
9.22   Distance between the bow fairlead and chain stopper/bracket: 9.0000   Yes   \$3.0000   Yes   Yes   \$3.0000   Yes   Yes	8.20	Safe Working Load (SWL) of chain stopper(s):		250 MT
Second   S	8.21	What is the maximum size chain diameter the bow stopper(s) can handle:		76 mm
A Stommy  If Inot, give details of size.   Stommy  If Inot, give description (Number, SWL and location):   Cansus 1 x 15 Tonnes MIDSHIP		· · · · · · · · · · · · · · · · · · ·		3000 mm
8.24   Derrick / Crane description (Number, SWL and location);	8.23	Is bow chock and/or fairlead of enclosed type of OCIMF recommended size (600mm x 450mm)? If not, give details of size:		Yes
MIDSHIP   Ship Transfer (STS)   Ship Transfer (State (Petroleum or Liquified Gas, as applicable)   Ship Transfer Guide (Petroleum or Liquified Gas, as applicable)   Ship Transfer Guide (Petroleum or Liquified Gas, as applicable)   Ship Transfer Guide (Petroleum or Liquified Gas, as applicable)   Ship Transfer Guide (Petroleum or Liquified Gas, as applicable)   Ship Transfer Guide (Petroleum or Liquified Gas, as applicable)   Ship Transfer Guide (Petroleum or Liquified Gas, as applicable)   Ship Transfer Guide (Petroleum or Liquified Gas, as applicable)   Ship Transfer Guide (Petroleum or Liquified Gas, as applicable)   Ship Transfer Guide (Petroleum or Liquified Gas, as applicable)   Ship Transfer Guide (Petroleum or Liquified Gas, as applicable)   Ship Transfer Guide (Petroleum or Liquified Gas, as applicable)   Ship Transfer Guide (Petroleum or Liquified Gas, as applicable)   Ship Transfer Guide (Petroleum or Liquified Gas, as applicable)   Ship Transfer Guide (Petroleum or Liquified Gas, as applicable)   Ship Transfer Guide (Petroleum or Liquified Gas, as applicable)   Ship Transfer Guide (Petroleum or Liquified Gas, as applicable)   Ship Transfer Guide (Petroleum or Liquified Gas, as applicable)   Ship Transfer Guide (Petroleum or Liquified Gas, as applicable)   Ship Transfer Guide (Petroleum or Liquified Gas, as applicable)   Ship Transfer Guide (Petroleum or Liquified Gas, as applicable)   Ship Transfer Guide (Petroleum or Liquified Gas, as applicable)   Ship Transfer Guide (Petroleum or Liquified Gas, as applicable)   Ship Transfer Guide (Petroleum or Liquified Gas, as applicable)   Ship Transfer Guide Gas, as applicable)   Ship Transfer Guide (Petroleum or Liquified Gas, as applicable)   Ship Transfer Guide Gas, as applicable)   Ship Transfer Cutter (Petroleum or Liquified Gas, as applicable		·	·	
Ship Transfer (STS)  2.8				
8.26 Does vessel comply with recommendations contained in OCIMP/ICS Ship To Ship To Ship  9. MISCELLANEOUS  Engire Room  1. What type of fuel is used for main propulsion? HO 380 CST  9. What type of fuel is used in the generating plant? HO 380 CST  9. Spacing of bunker tanks - IFO and MDO/MGO ST21.500 m3 R721.500 m3 R28.980 0.000  9. Spacing of bunker tanks - IFO and MDO/MGO Fixed Pitch  Insurance  9. P & I Club - Full Style: GARD ARNDAL, NORWAY REVISED AND ARNDAL AND ARNDAL A				5 m
9. MISCELLANEOUS  Engire Room  9. What type of fuel is used for main propulsion? 9. What type of fuel is used in the generating plant? 9. Vhat type of fuel is used in the generating plant? 9. Vhat type of fuel is used in the generating plant? 9. Vhat type of fuel is used in the generating plant? 9. Vhat type of fuel is used in the generating plant? 9. Vhat type of fuel is used in the generating plant? 9. Vhat type of fuel is used in the generating plant? 9. Vhat type of fuel is used in the generating plant? 9. Vhat type of fuel is used in the generating plant? 9. Vhat type of fuel is used in the generating plant? 9. Vhat type of fuel is used in the generating plant? 9. Vhat type of fuel is used in the generating plant? 9. Vhat type of fuel is used in the generating plant? 9. Visually of the plant is used in the gener			¥	
Minat type of fuel is used for main propulsion?	8.26			Yes
9.1 What type of fuel is used for main propulsion? HO 380 CST 9.2 What type of fuel is used in the generating plant? HO 380 CST 9.3 Capacity of bunker tanks - IFO and MDO/MGO: 3721.500 m3 289.80 0.00 9.4 Is vessel fitted with fixed or controllable pitch propeller(s)? Fixed Pitch  Insurance 9.5 P & I Club - Full Style:  9.6 P & I Club - Full Style:  9.7 Data and place of last Port State Control inspection:  9.8 Any outstanding deficiencies as reported by any Port State Control:  9.9 If yes, provide details:  9.1 Has vessel been involved in a pollution, grounding, serious casualty or collision incident during the past 12 months? If yes, full description:  9.1 Last three cargoes / charterers / voyages (Last / 2nd Last / 3rd Last):  9.2 Date/Place of last SIRE Inspection:  9.3 Date/Place of last SIRE Inspection:  9.4 Date/Place of last SIRE Inspection:  9.5 Place of last SIRE Inspection:  9.6 Pacent Oil company inspections/screenings (To the best of owners knowledge and without guarantee of acceptance for future business):  **Blanket**  **Blanket**  **Planket**  **Planket	9.	MISCELLANEOUS		
9.2 What type of fuel is used in the generating plant? 9.3 capacity of bunker tanks - IFO and MDO/MGO: 9.4 Is vessel fitted with fixed or controllable pitch propeller(s)? 9.5 P. 8 I Club - Full Style: 9.6 P. 8 I Club - Full Style: 9.7 QARD P. 8 I Club - Full Style: 9.8 P. 8 I Club - Full Style: 9.8 P. 8 I Club coverage - pollution liability coverage: 9.9 P. 8 I Club coverage - pollution liability coverage: 9.0 P. 8 I Club coverage - pollution liability coverage: 9.1 Qard D. Fax: +47 37 02 48 10	Engi	ne Room		
9.3 Capacity of bunker tanks - IFO and MDO/MGO: 9.4 Is vessel fitted with fixed or controllable pitch propeller(s)?  Insurance  9.5 Pa I Club - Full Style: 9.6 Pa I Club - Full Style: 9.7 Capacity of bunker tanks - IFO and MDO/MGO: 9.8 Pa I Club - Full Style: 9.9 Pa I Club - Full Style: 9.9 Pa I Club - Full Style: 9.9 Pa I Club coverage - pollution liability coverage: 9.1 Date and place of last Port State Control inspection: 9.7 Date and place of last Port State Control inspection: 9.8 Any outstanding deficiencies as reported by any Port State Control: 9.8 Any outstanding deficiencies as reported by any Port State Control: 9.1 It has vessel been involved in a pollution, grounding, serious casualty or collision incident during the past 12 months? If yes, full description: 9.11 Last three cargoes / charterers / voyages (Last / 2nd Last / 3rd Last): 9.12 Date/Place of last SIRE Inspection: 9.13 Date/Place of last SIRE Inspection: 9.14 Recent Oil company inspections: 9.15 Date/Place of last CDI Inspection: 9.16 Place of last CDI Inspection: 9.17 Place of last CDI Inspection: 9.18 Recent Oil company inspections: 9.19 Planker "approvals" are no longer given by Oil Majors and ships are accepted for the voyage on a case by case basis.  Version 3 (INTERTANKO / Q88.)	9.1	What type of fuel is used for main propulsion?	HO 380 CST	
Severage	9.2	What type of fuel is used in the generating plant?	HO 380 CST	
Insurance	9.3	Capacity of bunker tanks - IFO and MDO/MGO:	3721.500 m3	289.800 m3 0.000 m3
9.5 P & I Club - Full Style:  GARD  GARD P&I (Bermuda Ltd) Servicebox 600, NO-4809 ARENDAL, NORWAY Tel: +47 37 019 100 Fex: +47 37 02 48 10 Web: www.gard.no  9.6 P & I Club coverage - pollution liability coverage:  1000000000 US\$  Port State Control  Jan 29, 2012 / Texas City  No  9.7 Date and place of last Port State Control inspection:  9.8 Any outstanding deficiencies as reported by any Port State Control:  9.9 If yes, provide details:  Recent Operational History  9.10 Has vessel been involved in a pollution, grounding, serious casualty or collision incident during the past 12 months? If yes, full description:  Pollution: No, Grounding: Yes, 4/27/12 Vessel has smelt bottom outbot Mississippi river in ballast and has come clear on own providence of the past 12 months? If yes, full description:  9.11 Last three cargoes / charterers / voyages (Last / 2nd Last / 3rd Last):  Vetting  9.12 Date/Place of last SIRE Inspection:  9.13 Date/Place of last SIRE Inspection:  9.14 Recent Oil company inspections/screenings (To the best of owners knowledge and without guarantee of acceptance for future business):  **Blanket "approvals" are no longer given by Oil Majors and ships are accepted for the voyage on a case by case basis.  Version 3 (INTERTANKO / Qa8 at the part of the past of the past of the polyage of the po	9.4	Is vessel fitted with fixed or controllable pitch propeller(s)?	Fixed Pitch	
GARD P8. (Germuda Ltd) Servicebox 600, NO-4809 ARENDAL NORWAY Tel: +47 37 01 91 00 Fax: +47 37 02 48 10 Fax: +47 37 12 Fax: +47 27 12 Fax: +47 37 12 Fax: +47 37 12 Fax: +47 27 12 Fax: +47 37 12 Fax: +47 27 12 Fax:	Insu	'ance		
Port State Control 9.7 Date and place of last Port State Control inspection: 9.8 Any outstanding deficiencies as reported by any Port State Control: 9.9 If yes, provide details: N/A  Recent Operational History 9.10 Has vessel been involved in a pollution, grounding, serious casualty or collision incident during the past 12 months? If yes, full description: 9.11 Last three cargoes / charterers / voyages (Last / 2nd Last / 3rd Last): 9.12 Date/Place of last SIRE Inspection: 9.13 Date/Place of last CDI Inspection: 9.14 Recent Oil company inspections/screenings (To the best of owners knowledge and without guarantee of acceptance for future business):  **********************************	9.5	P & I Club - Full Style:	GARD P&I (Bermuda Ltd) Servicebox 600, NO-4809 ARENDAL, NORWAY Tel: +47 37 01 91 00 Fax: +47 37 02 48 10	
9.7 Date and place of last Port State Control inspection: 9.8 Any outstanding deficiencies as reported by any Port State Control: 9.9 If yes, provide details:    No	9.6	P & I Club coverage - pollution liability coverage:	1000000000 US\$	
9.8 Any outstanding deficiencies as reported by any Port State Control: 9.9 If yes, provide details:  Recent Operational History 9.10 Has vessel been involved in a pollution, grounding, serious casualty or collision incident during the past 12 months? If yes, full description: 9.11 Last three cargoes / charterers / voyages (Last / 2nd Last / 3rd Last):  Vetting 9.12 Date/Place of last SIRE Inspection: 9.13 Date/Place of last CDI Inspection: 9.14 Recent Oil company inspections/screenings (To the best of owners knowledge and without guarantee of acceptance for future business)*:  **Blanket "approvals" are no longer given by Oil Majors and ships are accepted for the voyage on a case by case basis.  Version 3 (INTERTANKO / Q88.)	Port	State Control		
9.9 If yes, provide details:  Recent Operational History 9.10 Has vessel been involved in a pollution, grounding, serious casualty or collision incident during the past 12 months? If yes, full description:  Pollution: No , Grounding: Yes , 4/27/12 Vessel has smelt bottom outbord Mississippi river in ballast and has come clear on own processing or collision: No , 9.11 Last three cargoes / charterers / voyages (Last / 2nd Last / 3rd Last):  Contact owner for details  Vetting 9.12 Date/Place of last SIRE Inspection: 9.13 Date/Place of last CDI Inspection: 9.14 Recent Oil company inspections/screenings (To the best of owners knowledge and without guarantee of acceptance for future business)*:  *Blanket "approvals" are no longer given by Oil Majors and ships are accepted for the voyage on a case by case basis.  Version 3 (INTERTANKO / Q88 and part of the service of the contact owner for details)  Version 3 (INTERTANKO / Q88 and part of the contact owner for details)	9.7	Date and place of last Port State Control inspection:	Jan 29, 2	2012 / Texas City
Recent Operational History  9.10 Has vessel been involved in a pollution, grounding, serious casualty or collision incident during the past 12 months? If yes, full description:  Pollution: No , Grounding: Yes , 4/27/12 Vessel has smelt bottom outbor Mississippi river in ballast and has come clear on own possible past 12 months? If yes, full description:  Serious casualty: No , Collision: No , Collision: No ,  9.11 Last three cargoes / charterers / voyages (Last / 2nd Last / 3rd Last):  Contact owner for details  Vetting  9.12 Date/Place of last SIRE Inspection: 9.13 Date/Place of last CDI Inspection: 9.14 Recent Oil company inspections/screenings (To the best of owners knowledge and without guarantee of acceptance for future business)*:  *Blanket "approvals" are no longer given by Oil Majors and ships are accepted for the voyage on a case by case basis.  Version 3 (INTERTANKO / Q88.4)	9.8	Any outstanding deficiencies as reported by any Port State Control:		No
9.10 Has vessel been involved in a pollution, grounding, serious casualty or collision incident during the past 12 months? If yes, full description:  9.11 Last three cargoes / charterers / voyages (Last / 2nd Last / 3rd Last):  Contact owner for details  Vetting  9.12 Date/Place of last SIRE Inspection:  9.13 Date/Place of last CDI Inspection:  9.14 Recent Oil company inspections/screenings (To the best of owners knowledge and without guarantee of acceptance for future business)*:  *Blanket "approvals" are no longer given by Oil Majors and ships are accepted for the voyage on a case by case basis.  Version 3 (INTERTANKO / Q88.)	9.9	If yes, provide details:	N/A	
incident during the past 12 months? If yes, full description:  Grounding: Yes, 4/27/12 Vessel has smelt bottom outbout Mississippi river in ballast and has come clear on own properties.  Serious casualty: No, Collision: No,  9.11 Last three cargoes / charterers / voyages (Last / 2nd Last / 3rd Last):  Contact owner for details  Vetting  9.12 Date/Place of last SIRE Inspection:  9.13 Date/Place of last CDI Inspection:  9.14 Recent Oil company inspections/screenings (To the best of owners knowledge and without guarantee of acceptance for future business)*:  *Blanket "approvals" are no longer given by Oil Majors and ships are accepted for the voyage on a case by case basis.  Version 3 (INTERTANKO / Q88.)	Rece	nt Operational History		
Vetting         9.12 Date/Place of last SIRE Inspection:       Jul 28, 2012 / Chalmette         9.13 Date/Place of last CDI Inspection:       N/A         9.14 Recent Oil company inspections/screenings (To the best of owners knowledge and without guarantee of acceptance for future business)*:       Contact owner for details.         *Blanket "approvals" are no longer given by Oil Majors and ships are accepted for the voyage on a case by case basis.    Version 3 (INTERTANKO / Q88.0)	9.10	Has vessel been involved in a pollution, grounding, serious casualty or collision incident during the past 12 months? If yes, full description:	Grounding: Yes , 4/27/12 Vessel has smelt bottom outbound Mississippi river in ballast and has come clear on own power Serious casualty: No ,	
Vetting         9.12 Date/Place of last SIRE Inspection:       Jul 28, 2012 / Chalmette         9.13 Date/Place of last CDI Inspection:       N/A         9.14 Recent Oil company inspections/screenings (To the best of owners knowledge and without guarantee of acceptance for future business)*:       Contact owner for details.         *Blanket "approvals" are no longer given by Oil Majors and ships are accepted for the voyage on a case by case basis.    Version 3 (INTERTANKO / Q88.0)	9.11	Last three cargoes / charterers / voyages (Last / 2nd Last / 3rd Last):		
9.12 Date/Place of last SIRE Inspection:  9.13 Date/Place of last CDI Inspection:  9.14 Recent Oil company inspections/screenings (To the best of owners knowledge and without guarantee of acceptance for future business)*:  *Blanket "approvals" are no longer given by Oil Majors and ships are accepted for the voyage on a case by case basis.  Version 3 (INTERTANKO / Q88.4)			å	
9.14 Recent Oil company inspections/screenings (To the best of owners knowledge and without guarantee of acceptance for future business)*:  *Blanket "approvals" are no longer given by Oil Majors and ships are accepted for the voyage on a case by case basis.  Version 3 (INTERTANKO / Q88.4)	9.12	Date/Place of last SIRE Inspection:	Jul 28, 2012 / Chalmette	
without guarantee of acceptance for future business)*:  *Blanket "approvals" are no longer given by Oil Majors and ships are accepted for the voyage on a case by case basis.  Version 3 (INTERTANKO / Q88.6)	9.13	Date/Place of last CDI Inspection:	N/A	
the voyage on a case by case basis.  Version 3 ( <u>INTERTANKO</u> / <u>Q88.</u>	9.14	Recent Oil company inspections/screenings (To the best of owners knowledge and without guarantee of acceptance for future business)*:	Contact owner for details.	
			Ve	rsion 3 ( <u>INTERTANKO</u> / <u>Q88.com</u> )
ED_002238_00001575-00006			EC	0 002238 00001575-00006